

26452 11 DEC 62

S E C R E T

LS
DDO
TSO/PA

25X1A

25X1A DIRECTOR

OSA/TCO (1-2-3-4-5-6-7-8)

TO: 1035Z 11 DEC 62

EDD
WER
KB
RLP
RDO
PAG

PRHIORITY

SAH

IN 58859

25X1A

PRITY

25X1A

1. G-3221/9693

25X1A

2. 9R/0-11-6000/UNK/9L/0-11-6000/172-10-9-6-1

3. D-19/4/75 DEGREE F/HTA-2

4. 2,02

25X1A

5. GOOD/GOOD/GOOD

6. TAKE RECEIVED 36/1617Z IN STEEL BOXES, CONDITION GOOD.
CONSIDERABLE NUMBER OF WATER SPOTS DUE TO LACK OF TRAINING ON HTA-2'S

NO TEST TAKE AVAILABLE TO OPERATE EQUIPMENT OR CHECKOUT PERSONNEL.
DUE TO TERRAIN CONDITIONS AND POOR MAPS CONSIDERABLE TROUBLE

25X1A EXPERIENCED IN LOCATING PHOTOGRAPHY. RECOMMEND THAT

25X1A

BE FURNISHED

TO AID IN PHOTO INTERPRETATION IN ALL

25X1A FUTURE OPERATIONS. FILM CREASE 9L, 2128. FILM DAMAGED IN
PROCESSOR, 9R 782 THROUGH 787, DUE TO BAD PRE-SPLICE. CHECK DATA
CHAMBER. CHAMBER RECORDING OVER EXPOSED. NO CAMERA MALFUNCTIONS
NOTED. DO NOT REPEAT DO NOT RECOMMEND CHANGE OF EXPOSURE OR FILTER.

25X1A

S E C R E T

25X1A

S E C R E T

[REDACTED] (IN 58859)

PAGE TWO

25X1A

DUE TO ROTATION OF EXPERIENCED PERSONNEL REQUEST [REDACTED] BE FURNISHED
TEST TAKE TO BE USED FOR TRAINING AND MAINTAINING PROFICIENCY OF
PROCESSING PERSONNEL AND EQUIPMENT. [REDACTED]

25X1A

25X1A ARRIVED [REDACTED] DURING EARLY PART OF [REDACTED] PROCESSING PHASE.
SITSUM TRANSMITTED 2230 HOURS, 7 DEC 62 LOCAL.

25X1A

7. NOT ACCOMPLISHED.
8. TO HQS COURIER ON 9 DEC 62.

END OF MESSAGE

S E C R E T

Approved For Release 2002/11/14 : CIA-RDP89B00569R000200030061-3

25X1A

Approved For Release 2002/11/14 : CIA-RDP89B00569R000200030061-3